



INSTALLATION MANUAL

Roma-1



TOOL PICTURE





Accessory list





1





2





3



4





5




Roma-2

Pencil	Cross screw driver	Drill machine	Tape measure	Silicon gel
Inner hexagon spanner (In the package)	Scissors	Level ruler	Rubber hammer	

x1	x1	x1	x1	x1
x2	x1	x2	x1	x2
x1	x1	4*16 x2	4*30 x4	x12
4*10 x2	x2	x4	x2	x1
x1	x1	4*30 x8		





1





	Amm	Cmm
500	485-495	496-506
600	585-595	596-606
700	685-695	696-706
800	785-795	796-806
900	885-895	896-906
1000	985-995	996-1006
1100	1085-1095	1096-1106
1200	1185-1195	1196-1206
1300	1285-1295	1296-1306
1400	1385-1395	1396-1406

	Bmm	Dmm
700	685-700	688-703
800	785-800	788-803
850	835-850	838-853
900	885-900	888-903
950	935-950	938-953
1000	985-1000	988-1003
1050	1035-1050	1038-1053
1100	1085-1100	1088-1103
1150	1135-1150	1138-1153
1200	1185-1200	1188-1203



2





3



4




5






INSTALLATION MANUAL

Roma-3


TOOL PICTURE



Accessory list





1





	Amm	Cmm
700	685-700	696-711
800	785-800	796-811
850	835-850	846-861
900	885-900	896-911
950	935-950	946-961
1000	985-1000	996-1011
1050	1035-1050	1046-1061
1100	1085-1100	1096-1111
1150	1135-1150	1146-1161
1200	1185-1200	1196-1211

	Bmm	Dmm
700	685-700	696-711
800	785-800	796-811
850	835-850	846-861
900	885-900	896-911
950	935-950	946-961
1000	985-1000	996-1011
1050	1035-1050	1046-1061
1100	1085-1100	1096-1111
1150	1135-1150	1146-1161
1200	1185-1200	1196-1211


2



3



4



5

